



This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

[illegible]

Give Details of Any Faults	Rectification Work Carried Out
No earth bond at gas meter	Informed responsible person to put earth bond at gas meter

CP12	
	Has flue cap been put back?

Signatures

Signed		Received By		Date	18/10/2024
Print Name	Abu Mazumder	Print Name	Nicolae buse	Next Inspection Date	18/10/2025